

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- BLURRY OR ILLEGIBLE TEXT
- SKEWED/SLATED IMAGES
- COLORED PHOTOS
- BLACK OR VERY DARK BLACK AND WHITE PHOTOS
- UNDECIPHERABLE GRAY SCALE DOCUMENTS


## **IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




2/23

【Fig.2】




【Fig.3】




4/23

【Fig.4】




【Fig.5】.




6/23

【Fig.6】



7/23


【Fig.7】





8/23

【Fig.8】




$$(\text{eccentricity}) = \frac{L0 - L1}{L0}$$

Actual ground contact length L1 is smaller than L0 (when eccentricity is zero) because of eccentricity.


9/23

【Fig.9】




10/23


【Fig.10】




【Fig.11】



【Fig. 12】




【Fig.13】




14/23

【Fig.14】




【Fig.15】







16/23

【Fig.16】









19/23

【Fig.19】




FOR OFFICIAL USE ONLY

【Fig.20】




21/23

【Fig.21】



[Fig. 22]



【Fig.23】

